

TITLE:	<u>LIGHTIN</u>	<u>G — AUXILIA</u>	<u>ARY</u>
VERSION:	V2.2		
DATE PUBLISHED:	06/23/2	12	
DEFINITION:	Lighting (that is assantia	l to safety in the event of primary power supply failure.
PURPOSE:	Assist pec	ople egress a b	uilding in the event of an emergency.
COMMON COMPONENTS:	Rechargea	able battery ba	ckup; Light bulb; Circuits; Lamps; Test button; Housing assembly
LOCATION:		Unit	None
	\boxtimes	Inside	Throughout the Inside.
	\boxtimes	Outside	Throughout the Outside.
MORE INFORMATION:	Exit signs	, exposed wiri	ng, and cut hazards are related standards
DEFICIENCY 1:	Auxiliary light	ing fails to illu	uminate when tested.
LOCATION:	 Inside		Outside
DEFICIENCY 2:	Auxiliary light	ting component	t is damaged or missing.
LOCATION:	 Inside		Outside

Deficiency I - Inside: Auxiliary lighting fails to illuminate when tested.

DEFICIENCY CRITERIA: After pressing the test button, the auxiliary light does not illuminate.

HEALTH AND SAFETY DETERMINATION: Severe Non-Life- The Severe Non-Life-Threatening category includes deficiencies that, if evident in the home or

Threatening on the property, present a high risk of permanent disability, or serious injury or illness, to a

resident; or the physical security or safety of a resident or their property would be seriously

compromised.

CORRECTION TIMEFRAME: 24 hours

HCV PASS / FAIL: Fail

HCV CORRECTION TIMEFRAME: 30 days

INSPECTION PROCESS:

OBSERVATION: - Look to ensure that the device responds to the test and illuminates.

REQUEST FOR HELP: - Ask the POA for the location of the backup battery, if applicable.

ACTION: - Engage the test button.

- Verify the emergency light illuminates for the entire time the test button is engaged.

- Verify all light sources illuminate during the test.

MORE INFORMATION: - Some backup batteries may be located remotely.

- Combination auxiliary light and exit sign devices must be recorded as two individual deficiencies, each within its

respective inspectable item.

Deficiency I - Outside: Auxiliary lighting fails to illuminate when tested.

DEFICIENCY CRITERIA: After pressing the test button, the auxiliary light does not illuminate.

HEALTH AND SAFETY DETERMINATION: Severe Non-Life- The Severe Non-Life-Threatening category includes deficiencies that, if evident in the home or

Threatening on the property, present a high risk of permanent disability, or serious injury or illness, to a

resident; or the physical security or safety of a resident or their property would be seriously

compromised.

CORRECTION TIMEFRAME: 24 hours

HCV PASS / FAIL: Fail

HCV CORRECTION TIMEFRAME: 30 days

INSPECTION PROCESS:

OBSERVATION: - Look to ensure that the device responds to the test and illuminates.

REQUEST FOR HELP: - Ask the POA for the location of the backup battery, if applicable.

ACTION: - Engage the test button.

- Verify the emergency light illuminates for the entire time the test button is engaged.

- Verify all light sources illuminate during the test.

MORE INFORMATION: - Some backup batteries may be located remotely.

- Combination auxiliary light and exit sign devices must be recorded as two individual deficiencies, each within its

respective inspectable item.

Deficiency 2 - Inside: AUXILIARY LIGHTING COMPONENT IS DAMAGED OR MISSING.

DEFICIENCY CRITERIA: Auxiliary lighting component is damaged (i.e., visibly defective).

Auxiliary lighting component is missing (i.e., evidence of prior installation, but now not present or is incomplete).

HEALTH AND SAFETY DETERMINATION: Deficiencies critical to habitability but not presenting a substantive health or safety risk to Advisory

CORRECTION TIMEFRAME: N/A HCV PASS / FAIL: Pass

HCV CORRECTION TIMEFRAME: N/A

INSPECTION PROCESS:

Look at the auxiliary light to: OBSERVATION:

> - Identify if the glass or placard is damaged or missing; Determine if the mounting bracket is damaged;

- Determine if it is hanging loose from its mount (i.e., not securely affixed); and

- Identify any evidence indicating a component was installed but is missing at the time of inspection.

REQUEST FOR HELP:

- None

ACTION:

MORE INFORMATION: - If the entire auxiliary lighting fixture is missing, then it should be evaluated under Deficiency 1.

- If the auxiliary lighting fixture does not illuminate, then it should be evaluated under Deficiency I.

- Combination auxiliary lighting and exit sign devices must be recorded as two individual deficiencies, each under its respective standard.

DEFICIENCY 2 - Outside: AUXILIARY LIGHTING COMPONENT IS DAMAGED OR MISSING.

DEFICIENCY CRITERIA: Auxiliary lighting component is damaged (i.e., visibly defective).

Auxiliary lighting component is missing (i.e., evidence of prior installation, but now not present or is incomplete).

HEALTH AND SAFETY DETERMINATION: Deficiencies critical to habitability but not presenting a substantive health or safety risk to Advisory

CORRECTION TIMEFRAME: N/A HCV PASS / FAIL: Pass

HCV CORRECTION TIMEFRAME: N/A

INSPECTION PROCESS:

Look at the auxiliary light to: OBSERVATION:

> - Identify if the glass or placard is damaged or missing; Determine if the mounting bracket is damaged;

- Determine if it is hanging loose from its mount (i.e., not securely affixed); and

- Identify any evidence indicating a component was installed but is missing at the time of inspection.

REQUEST FOR HELP: - None

ACTION:

MORE INFORMATION: - If the entire auxiliary lighting fixture is missing, then it should be evaluated under Deficiency 1.

- If the auxiliary lighting fixture does not illuminate, then it should be evaluated under Deficiency I.

- Combination auxiliary lighting and exit sign devices must be recorded as two individual deficiencies, each under its

respective standard.



SUMMARY OF CHANGES

TITLE: LIGHTING — AUXILIARY

VERSION: V2.2

DATE PUBLISHED: 06/23/22

FIELD	Change	Version	Date
	Abbreviated published version	V2.2	2022-06-23
Name Variants	Removed from published version	-	
Common Materials	Removed from published version		
Rationale	Removed from published version		
Tools or Equipment	Removed from published version		
Deficiency 2		V2.2	2022-06-23
Health and Safety Determination	Inside: Relabeled from "N/A" to "Advisory" Outside: Relabeled from "N/A" to "Advisory"		
Location	Revised inspectable locations	V2.1	2021-04-02
More Information	Added field	V2.1	2021-04-02
Deficiency I		V2.1	2021-04-02
Title	Added inspectable location		
Health and Safety Determination	Inside & Outside: Revised determination and description		
Correction Timeframe	Inside & Outside: Revised correction time frame		
Rationale	Inside and Outside: Revised rationale categories, types, and explanations; added standardized codes and descriptions		
Inspection Process	Inside and Outside: Revised Action		
Deficiency 2		V2.1	2021-04-02
Title	Revised title; added inspectable location		
Deficiency Criteria	Inside & Outside: Revised deficiency criteria		
Health and Safety Determination	Inside & Outside: Revised determination and description	······	



Correction Timeframe	Inside & Outside: Revised correction time frame		
HCV Pass / Fail	Inside & Outside: Revised input to "Pass"		
Rationale	Inside and Outside: Revised rationale categories, types, and explanations; added standardized codes and descriptions		
Inspection Process	Inside and Outside: Revised Observation, Request for Help, Action, and More Information		
Deficiency I		V2.0	2020-10-28
Health and Safety Determination	Added standardized description		
HCV Pass / Fail	Field added; response input as "Fail"		
Deficiency 2		V2.0	2020-10-28
Health and Safety Determination	Added standardized description		
HCV Pass / Fail	Field added; response input as "Fail"		
Overall Formatting	Complete rework of document format and layout	VI.3	2020-07-31
Definition	Revised definition	VI.3	2020-07-3
Purpose	Field added	VI.3	2020-07-3
More Information	Field added	VI.3	2020-07-3
Deficiency I	Separated by inspectable locations — Inside	VI.3	2020-07-3
Title	Added inspectable locations		
Health and Safety Determination	Added standardized description		
Health and Safety Determination Correction Timeframe			
	Added standardized description		
Correction Timeframe	Added standardized description Field added; response input as "Within 30 days"		
Correction Timeframe HCV — Correction Timeframe	Added standardized description Field added; response input as "Within 30 days" Field added; response input as "Within 30 days" Revised rationale categories, types, and explanations; added standardized codes and		
Correction Timeframe HCV — Correction Timeframe Rationale	Added standardized description Field added; response input as "Within 30 days" Field added; response input as "Within 30 days" Revised rationale categories, types, and explanations; added standardized codes and descriptions		
Correction Timeframe HCV — Correction Timeframe Rationale Inspection Process Tools or Equipment	Added standardized description Field added; response input as "Within 30 days" Field added; response input as "Within 30 days" Revised rationale categories, types, and explanations; added standardized codes and descriptions Revised observation, request for help, action, and more information	VI.3	2020-07-31
Correction Timeframe HCV — Correction Timeframe Rationale Inspection Process	Added standardized description Field added; response input as "Within 30 days" Field added; response input as "Within 30 days" Revised rationale categories, types, and explanations; added standardized codes and descriptions Revised observation, request for help, action, and more information Field added to deficiency	VI.3	2020-07-31



Deficiency 2	Added	VI-I	2019-11-26
Record Deficiency	Updated		
Inspection Process and Procedure	Updated		
How to Inspect	Updated	-	
Rationale	Updated		
Title	Updated		
Deficiency I	Updated	VI-I	2019-11-26
How to Locate	Updated	VI-I	2019-11-26
Common Locations	Updated	VI-I	2019-11-26
Abilities or Knowledge Needed	Updated	VI-I	2019-11-26
Most Common Components	Updated	VI-I	2019-11-26
Most Common Materials	Updated	VI-I	2019-11-26
Name Variants	Updated	VI-I	2019-11-26
Definition	Updated	VI-I	2019-11-26
Health and Safety Determinations	Updated following in-house review and public comment	VI-2	2019-12-26
Rationales	Updated following in-house review and public comment	VI-2	2019-12-26
Tools or Equipment	Field added to deficiency; response revised		
Inspection Process	Revised observation, request for help, action, and more information	-	
Rationale	Revised rationale categories, types, and explanations; added standardized codes descriptions	and	
HCV — Correction Timeframe	Field added; response input as "Within 30 days"		
Correction Timeframe	Field added; response input as "Within 30 days"		
Health and Safety Determination	Added standardized description		